A CONTROLLED CONT	LARGE COMMERCIAL PASSENGER VESSEL PERMITTED / WASTEWATER DISCHARGE UNDERWAY INSPECTION REPORT Alaska Department of Environmental Conservation Division of Water			Form: AK-LCPV-D-U	
STATE OF ALASEA				Last Updated 4.23.2024	
	SECTION	1: GENERAL			
Inspection Date(s):		Vessel Name:	Vessel Name:		
6/12/24 - 6/13/2024		Eurodam	Eurodam		
GP Auth #: 2013DB0004-0	0025	IMO No.:			
(Issue Date) 4/18/2022	9378448	9378448			
Inspection: \square Announced \square Unannounced.		Port of Departure		Sitka	
DEC Registration #: 2024-CS-0014		Port of Arrival		Ketchikan	
Arrival Time (at vessel):	Inspection Star	t	Inspectio	ı End	
1200	Date:6/12/202	4	Date: 6/13/2024		
Time 1300		Time: 0900		00	
Additional Information (e.g., access issues): No issues joining the vessel. The staff were expecting the inspector.					
Inspection Focus The inspe	ction focuses on complian	nce with general perm	nit requirem	nents.	
Past Compliance Follow-up Items: UYES NO					
ADEC Inspector(s)					
Inspector(s): Mark Chryss				Credentials Presented: ⊠YES □NO	
Vessel Contacts					
Name (Onboard): Neil Maitland Main (Main Office: [primary contact in EDMS]		
Title: Environmental Officer		Konstantin Konstantinov			
Vessel: Eurodam		Director of Environmental Operations and Policy			
			Holland American Line		
Email:	661-210-6296				
eudm-environmental office	er@hollandamerica.com	<u>kkonstantinov@</u> }	kkonstantinov@hagroup.com		

SECTION 2: DOCUMENTATION			
Passengers onboard (during this inspection): 2,256 pax and 831 crew			
Quality Assurance Project Plan (QAPP): Copy onboard? YES NO CLIA QAPP USED			
Vessel Specific Sampling Plan (VSSP): Copy onboard? XYES INO			
ADEC WW GP 2013DB-0004: Copy onboard? XYES INO			
USCG Discharge Authorization Copy onboard?			
Other Documents Reviewed: Environmental Schedule (One Ocean, a proprietary system that has environmental policies outlined for the company).			
LV WW Discharge General Permit (GP) – 2013DB-0004			
If applicable			
🖾 Underway 🗆 Stationary 🗆 Skagway			
Additional Terms and Conditions (Authorization Section 5, GP 4.3.2) (e.g., only GW in port, etc.):			
The Vessel only discharges underway (greater than 6 knots)			
Wastewater Discharge Logs			
WW Discharge Logs for previous 12 months available onboard? Yes.			
Any unauthorized discharges, spills, or non-compliance items?			
None.			
Is a Vessel environmental Voyage Plan available? XYES DNO			
If so: which elements are included in this plan?			
Wastewater discharges, fuel changeover, EGCS operations, incinerator operations, boiler blowdowns, food waste discharges.			

SECTION 3: WASTEWATER SYSTEM

Current status of the AWTS system: Operable

AWTS Details: Hamworthy MBR

Capacity of each unit (s): per manufacturer.

2 units total capacity of $720 \text{ M}^3/\text{day}$

All equipment operable/ in-use. \Box YES \Box NO

All monitoring operable/ in-use \boxtimes YES \square NO

General Notes regarding AWTS: The Wastewater treatment plant was observed to be operational with no indications of alarms or faults on the local control panel.

Chemical Additives used as component of AWTS: \Box YES \boxtimes NO

Bio sludge Handling – Liquid biomass is stored in a dedicated tank and is discharged outside of 12NM. The vessel discharges about twice weekly.

Luiouaiii	www.Discharge vesser inspection	0/12/2024-0/15/2024
UNTREATED WW – Galley and I discharged outside of 12 NM.	Laundry have their own dedicated graywate	er tanks. The tanks are
Untreated and treated graywater car	be discharged to shoreside facilities.	
	Ū	
Separate GW & Mix WW discha	rges \Box More than one permeate outfall	
Describe switchover procedure: NA	Δ	
2 units have one permeate outfall co	ombined	
Discharge procedures		
Describe vessel's WW discharge pro	ocedures:	
When a planned discharge occurs, t	lace. All Environmental operations are disc he bridge will notify the engineers that they Iraffic lite system is in place. The light is it nen they are not.	y are in the correct position and
	are closed while in non discharge status? manually operated. The monitoring syster	n indicates whether a valve is in
0	rwise) does the crew use when discharging ne Ocean Program (Proprietary software th	
How does vessel calculate discharge volumes are calculated based on cha	e volumes: The permeate volumes are flow ange in tank level and elapsed time.	v metered for discharge. All other
Electronic Logs: XYES DNO		
NAPA electronic logs are used		
MSD Maintenance Log: The wastev	vater treatment plant has planned and unpl e database. A spare parts inventory is main	
	y, laundry, etc.) handled that are not treated e of 12 NM. Bio digestor water is untreate	

Regulatory Effluent Sampling

GW=Greywater and BW=Blackwater (i.e., sewage)

WW sample taken during this inspection? \Box YES \Box NO

Was sample event viewed by inspector?

YES
NO

General observations: N/A, no samples were taken during the inspection. However, samples were taken on the 6/12/24 by Admiralty Environmental (conventional sample) prior to the inspector's arrival. The following are the results of the sample:

Parameter	Result	Units	Limit
pH	7.46	SU	6-9
Free Chlorine	<0.1	mg/L	N/A
Total Chlorine	<0.1	mg/L	0.1
Biological Oxygen Demand (BOD)	14	mg/L	60
Total Suspended Solids (TSS)	<4.0	mg/L	150
Fecal Coliform (FC)	<2.0	FC/100mL	40

Lab Report Attachment

Vessel Process (Effluent) Sampling:

Does the vessel conduct process sampling? ⊠YES □NO Notes: Sampling onboard is conducted every 3 days. pH, Chlorine, COD BOD, TSS FC

SECTION 4: ADDITIONAL OBSERVATIONS

EPA VGP (Alaska signed off onto the 2013 EPA VGP)

Ballast Water / Invasive Species

Does the vessel engage in Ballast Water Operations while in AK waters? XYES NO

The vessel has a US approved ballast water treatment system. A calibration event took place in Juneau on 3 June 2024

Ballast Water Management – The vessel has an approved ballast water management plan.

Are Ballast Water tankage used for the storage of Wastewater? \square YES \square NO

There are 18 dual purpose (ballast water and wastewater storage) tanks onboard.

Internal biofouling -

Cathodic Protection \boxtimes YES \square NO

Hull Husbandry

Is underwater hull cleaning to be conducted in AK waters? \Box YES \boxtimes NO

When was the last underwater hull cleaning performed? \boxtimes Drydock \square Underwater

The vessel was drydocked in 5/2023 in Freeport Bahamas

WW Stream / Other Items

Incinerator – one incinerator onboard. Currently functioning. The vessel's policy is to only burn paper and medical waste.

Solid Waste Management – all waste collected and separated and reduced in volume by compaction or grinding and palletized and landed ashore outside of Alaska.

Haz-Mat Management – Haz mat waste is segregated and landed ashore to contracted service outside of Alaska.

Food Waste Management – Food waste is bio digested and stored in dedicated tanks and discharged outside of 12 NM. Food waste is logged with garbage. Hard food is crushed/ground and dehydrated and landed ashore as solid waste.

Marine Growth/Screening (Sea Strainers/Chests, etc) – The contents that is scraped and cleaned from sea strainers and piping is landed ashore with solid waste and recorded in the garbage log.

Boiler Blowdown – outside of 12 NM

Rec Water Management - Pool water is monitored for chlorine and discharged outside of 12 NM

Photo shop onboard: extstyle YES extstyle NO

Exhaust Gas Scrubber System

Exhaust Gas Scrubber System used? (VGP 2.2.26): 🛛 YES 🛛 NO

System: \Box HYBRID \boxtimes OPEN \Box CLOSED

EGCS units installed and corresponding Combustion sources.

Dedicated combustion sources to MGO (LSMGO)? All engines are equipped with EGCS. All engines operate on MGO and HFO.

Operational plan for EGCS use in AK Waters? (i.e., Where are scrubbers used during AK season, if using closed loop, describe bleed off discharges?): The EGCS are open loop systems. The plan for the use of EGCS (for arrival in to Ketchikan on this voyage) was to maneuver on HFO in open loop until the vessel was alongside and then to switch all loads over to engines running on MGO.

Fuel changeover – Fuel changeover points are identified in voyage environmental operations planning when they are needed.

ECGS Monitoring – A compliance computer is in place to collect the data that is used for required EPA compliance reporting. The exhaust gas is monitored by camera and reviewed for opacity exceedances.

Dock-Side + Underway Observations				
Potable Water bunkering: YES NO				
WW Discharge observed? YES NO				
\Box Pump Truck \Box City Sewer \Box Overboard				
Sheens/Discolorations observed? \boxtimes YES \square NO Agency Notified: \square USCG \boxtimes DEC-Water (in attendance)				
Describe: At 0615 on the morning of the 13 th of June, the inspector observed a cloudy effluent which left the surface of the water with a visible film, from the starboard side of the vessel. The cloudy discharge and associated film was observed continuously for more than 10 minutes and the surface remained cloudy for several minutes (first photo at 0615 and last at 0632). See photos in the photo addendum.				
Weather (Wind/Tides): At 6:15 am the winds were calm and the temperature was 50°F. There was no precipitation and the high tide was at 6:04 am.				
Any exterior activity (painting / deck wash etc.)? None observed.				
NON-VESSEL Observations: (Dock-side / Underway items not relating to vessel)				

None

SECTION 5: OVERVIEW

Inspection Observations

The inspector met with the Environmental officer (EO) shortly after boarding and discussed an agenda for the routine inspection. At 1300 the inspector met the EO in their office and reviewed documents, records and procedures for general permit compliance. At 1540hrs the inspector toured the solid waste handling facilities and food waste handling systems until 1600 hrs. At 1845hrs the inspector met again with the EO. The inspector observed the process of discharge operations and toured the machinery plant and completed the tour and work for the day at 1930hrs. The required documents and records were in order and accessible. The wastewater treatment plant was observed to be functioning with no indications of alarms on the local control panel. Solid waste handling facilities appeared to be clean and orderly.

Additional Comments

While the inspector was waiting to disembark the vessel at 0615 on the morning of the 13th of June, he observed a cloudy effluent which left the surface of the water with a visible film. The cloudy discharge and film was observed on the starboard side of the vessel. The cloudy discharge and associated film was observed continuously for more than 10 minutes and the surface remained cloudy for several minutes after (first photo at 0615 and last at 0632). The inspector notified the Environmental Officer and began to investigate what caused the condition. The Inspector met with the Captain of the vessel at 0700. The Captain had not been notified of the reported incident. There was no log book entry made or observation to follow up on the report of an apparent pollution incident. The EO had notified the Staff Chief Engineer (which is not the lead engineering officer) who had been showering at the time of the incident's reporting. The inspector shared the photos of the incident with the vessel's master (Captain) and requested to meet with the engineering staff and investigate. The operation of the exhaust gas cleaning system (EGCS) was occurring at the time the cloudy discharge and residual surface film was observed and reported. The inspector reviewed the EGCS computer data (a required component for the use of EGCS) and observed several alarm patterns associated with DG5 around the time and during the time of the observed cloudy water with a surface film between 6:15am and 6:32am. Times are shown below in UTC. The data below was requested as part of the follow-up of the witnessed cloudy discharge and surface film. The data was not provided in chronological order. However, the system "Major Malfunction" alarms occur prior to and during the time of the witnessed cloudy water discharge with film on the surface of the water. Photographs begin at 6:15am. Hower, the cloudy discharge and film on the surface of the water was first observed by another person (guest) and pointed out to the inspector so the event was happening prior to the first photo for an undetermined amount of time. The photos indicate an increase in the visible cloudy discharge and film on the surface at the corresponding time of the alarms.

l	24/06/13 12:21:56:707	DG5_DSX_ALMAJ_MAJMAL	DeSOx System: MAJOR MALFUNCTION	VALUE	ALARM
l	24/06/13 12:03:36:057	DG5_DSX_GEN_ALARM	DeSOx System: General Alarm	VALUE	ALARM
l	24/06/13 12:03:36:058	DG5_DSX_ALMAJ_MAJMAL	DeSOx System: MAJOR MALFUNCTION	VALUE	ALARM
l	24/06/13 12:03:36:059	LT06068_04P_LTV_	HFO STTLNG TKØ4P	Lim H2	150.
l	24/06/13 12:03:36:059	DG5_DSX_FLOW_RACK_2_A	lWater Analyzer Rack2 LOW FLOW ala	armVALUE	ALARM
l	24/06/13 12:03:36:059	DG5_DSX_ALMIN_WASF	Water Analyzer Rack 2/3: FAULT	VALUE	ALARM
l	24/06/13 12:06:57:666	LT06068_04P_LTV_	HFO STTLNG TKØ4P	Lim H2	150.
l	24/06/13 12:22:06:963	DG5_DSX_GEN_ALARM	DeSOx System: General Alarm	VALUE	ALARM
l	24/06/13 12:22:11:733	DG5_DSX_GEN_ALARM	DeSOx System: General Alarm	VALUE	ALARM
l	24/06/13 12:22:11:734	DG5_DSX_ALMAJ_MAJMAL	DeSOx System: MAJOR MALFUNCTION	VALUE	ALARM
l	24/06/13 12:22:11:734	DG5_DSX_FLOW_RACK_2_A	lWater Analyzer Rack2 LOW FLOW ala	armVALUE	ALARM
L					



Photo taken at 0615



Photo taken at 0621


SECTION 6: FOLLOW-UP

Compliance Assistance Items

Observations from the investigation of the witnessed incident of the vessel discharging cloudy effluent that left a film on the surface of the water upon arrival in Ketchikan on 6/13/24, 0615hrs:

- The incident was reported by the ADEC inspector to the ship's Environmental Officer and after that the communications of the incident went directly to the Staff Chief Engineer, who was showering at the time he was notified. The event of a cloudy discharge that left a film on the surface of the water was never communicated to anyone on the bridge or to senior officers. No observation was made by anyone other than the inspector witnessing the event and the ship's Environmental Officer. No logbook entry of the reported incident was made. The ineffective reporting of the incident and compartmentalizing of information are concerning and warrant internal follow up by the operator, the USCG and the endorser (Class Society/Flag State) of the vessel's SMC.
- The Captain, the Chief Engineer and the Environmental Officer indicated that the incident was not a first-time occurrence and happens with frequency. There seemed to be no concern that this kind of incident was notable or required specific action to rectify the occurrences. The vessel's Captain, Chief Engineer and Environmental Officer follow company issued guidelines (photos of various EGCS washwater effluent conditions that the operator deems acceptable). The guidelines were presented as a justification, though no proactive use of the guidelines (periodically checking the effluent condition against the issued guidance) was observed by the inspector. There was no correlating condition presented (none of the company issued guidance examples matched the condition observed and photographed by the inspector). The machinery is indicating major malfunction and alarming. Best management practices (BMPs) are not applied to the operation of the EGCS that proactively address washwater quality.
- The alarm data collected indicates that a major malfunction of the system described as DeSOx occurred during the time of the witnessed cloudy effluent discharge and film on the surface of the water. The alarm data observed onboard shows the same alarms at previous maneuverings (vessel docking procedure). The EGCS is required by the IMO and USEPA to meet the performance criteria it was certified to which includes the standards of washwater turbidity, metals, nitrates, PH, PAH and other criteria. The IMO Resolution MEPC 259 (68) requires that periodic surveys be completed by the issuer and endorser of the MARPOL Annex VI certificate (Class Society or Flag State) to verify continued compliance of the EGCS. As the system is required to be surveyed, maintained and verified as operational, the operator shall have a class survey conducted and a report issued indicating that the malfunctioning EGCS has been properly repaired and is functioning as required by IMO resolution MEPC 259 (68) and all other applicable MEPCs required when EGCS is used for SOx Emissions Compliance Certification (SECC).
- These violations have been forward to EPA Region 10 (regulatory body for EGCS compliance) for enforcement.

Signature		
Inspector – Mark Chryss Credential Number: R-605 Phone: (907) 269-4720 E-mail: <u>mark.chryss@alaska.gov</u>	Mark Chuyes Date: 7/10/2024	
Reviewed By – Ben Eisenstein Credential Number: R-598 Phone: (907) 465-5161 E-mail: <u>ben.eisenstein@alaska.gov</u>	<i>BdA</i> Date: 7/10/2024	










Photo A	ddendum		
Photo 07	Photo 08		
	Membrano S. Cleaner Image: Cleaner I		
Wastewater treatment membrane bank	Wastewater treatment system local control panel		

